

Mobilink Business Solutions Division (BSD)

RF Operations

Link Commissioning Report



Media Type : PMP P2P Wimax Service Type : Internet VPN

CUSTOMER DETAILS

Installation Date: 11-Mar-19 RF Team detail: Kashif / Umair
UCID: 2019401969 Branch Code: _____
Name of Client: Integrated Units
Address: Integrated Units Pvt. Ltd-PFF Colony, Kutchery Road-Sialkot-P2P
Contact Person: Ruman Malik Designation: _____
Contact Detail: 3333369600

BS & SITE DETAILS

GPS: _____
IDU S.No.: 20480-0016947 Antenna Details: Integrated
ODU S.No.: 347SC18120045 ODU Mac Address: 00-09-02-16-18-18
Cable length (ft): 150 Grounding (ft): _____ Mast Details: 80 in. fts.
Iron Flexible Pipe (ft): 0 PVC Pipe (ft): _____ Building Height: _____ in. fts.
RDL 3000 SU: _____ Redline AN-80i: _____ RDL 3000 Enterprise:

CLIENT END EQUIPMENT DETAILS

GPS: _____
IDU S.No.: C17176582000001621 Antenna Details: Integrated
ODU S.No.: 347SC18240046 ODU Mac Address: 00:09:02:16:23:99
Cable length (ft): 140 Grounding (ft): _____ Mast Details: 50 in. fts.
Iron Flexible Pipe (ft): _____ PVC Pipe (ft): 40 Building Height: 24 in. fts.
RDL 3000 SU: _____ Redline AN-80i: _____ RDL 3000 Enterprise:

SITE FINDINGS

Check & Confirm the availability	AC	<input checked="" type="checkbox"/>	UPS	<input checked="" type="checkbox"/>	Pwr Socket	<input checked="" type="checkbox"/>
	Genset	<input checked="" type="checkbox"/>	Electrical Grounding	<input type="checkbox"/> N/A	Voltages	<input type="checkbox"/> N/A Volts
	Switch Port	<input checked="" type="checkbox"/>	Tower Grounding	<input type="checkbox"/> N/A	Voltages	<input type="checkbox"/> N/A Volts

Customer Comments

Proper IT Rack not available. So POE not hanged. Placed with other network devices.

This is to certify that above mentioned credential are verified and deployment is as per standard. Equipment handling details have been shared by deployment team.

Signature

Name: _____ Designation: _____ Date: _____

Note:-

- If deployed equipments are damaged or malfunctioned due to power surge then customer will bear the cost of replacement.
- No one is authorized to alter the configuration of the device other than Mobilink officials.
- Equipment should not be switched to frequencies other than ISM band, if applicable.
- Any misuse of equipment in shape of unlicensed use & mishandling will be considered customer's own responsibility and regulatory authorities can take legal action against defaulters.